
## **APPENDIX A**

## **ENGINEERING APPENDIX FIGURES 201-237**

Jacksonville Harbor Navigation Study, Duval County, Florida

DRAFT
INTEGRATED GENERAL REEVALUATION
REPORT II AND SUPPLEMENTAL
ENVIRONMENTAL IMPACT STATEMENT




JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

CHECKED BY: DATED: **MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 140+00 TO 142+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.






CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 143+00 TO 145+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.






CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 146+00 TO 148+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 149+00 TO 151+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.





CHECKED BY: DATED:


**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-42 STATION 152+00 TO CUT-43 STATION 2+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

**MARCH 2013** 

**CUT-43 STATION 3+00 TO 5+00** GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED: **MARCH 2013** 

**CUT-43 STATION 6+00 TO 8+00** GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

**MARCH 2013** 

**CUT-43 STATION 9+00 TO 11+00** GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-43 STATION 12+00 TO 14+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-43 STATION 15+00 TO 17+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.





CHECKED BY: DATED:


**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-43 STATION 18+00 TO 20+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS CUT-43 STATION 21+00 TO CUT-44 STATION 2+00** GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.





CHECKED BY: DATED:


**MARCH 2013** 

**DREDGING CROSS SECTIONS CUT-44 STATION 3+00 TO 5+00** GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.





CHECKED BY: DATED:


**MARCH 2013** 

**DREDGING CROSS SECTIONS CUT-44 STATION 6+00 TO 8+00** GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.






CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS CUT-44 STATION 9+00 TO 11+00** GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF






втм CHECKED BY: DATED: **MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-44 STATION 12+00 TO 14+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

**MARCH 2013** 

CUT-44 STATION 15+00 TO 17+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

**MARCH 2013** 

CUT-44 STATION 18+00 TO 20+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.






CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-44 STATION 21+00 TO 23+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE SHORELINE SYMBOL IS NOT SHOWN.






CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-44 STATION 24+00 TO 26+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

**MARCH 2013** 

CUT-44 STATION 27+00 TO 29+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

**MARCH 2013** 

CUT-44 STATION 30+00 TO 32+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

**MARCH 2013** 

CUT-44 STATION 33+00 TO 35+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.




JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

CHECKED BY: DATED:

**MARCH 2013** 

CUT-44 STATION 36+00 TO 38+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF






CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-44 STATION 39+00 TO 41+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

225




JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-44 STATION 42+00 TO 44+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

**MARCH 2013** 

CUT-44 STATION 45+00 TO 47+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SHORELINE SYMBOL IS NOT SHOWN.

227 SECTION ON SECTIONS WHERE APPROXIMATE



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

CHECKED BY: DATED:


**MARCH 2013** 

CUT-44 STATION 48+00 TO CUT-45 STATION 1+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS CUT-45 STATION 2+00 TO 4+00** GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.





CHECKED BY: DATED:


**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-45 STATION 5+00 TO 7+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.




JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS CUT-45 STATION 8+00 TO 10+00** GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.





CHECKED BY: DATED:


**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-45 STATION 11+00 TO 13+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

CHECKED BY: DATED:


**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-45 STATION 14+00 TO 16+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.





CHECKED BY: DATED:


**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-45 STATION 17+00 TO 19+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.






CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-45 STATION 20+00 TO 22+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.





CHECKED BY: DATED:


**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-45 STATION 23+00 TO 25+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

втм CHECKED BY: DATED:

**MARCH 2013** 

**DREDGING CROSS SECTIONS** CUT-45 STATION 26+00 TO 28+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.